

Volvo P1800(S) package tray plywood templates
Original plywood had 9mm thickness
Some holes (e.g. drive-in nuts for rear bench) may be missing

Angle between panels = 63°

